



Software Release Note for USB STA MAC X

This document is property of Ralink Technology, Inc. Transmittal, receipt, or possession of this document does not express, license, or imply any rights to use, sell, design, or manufacture from this information or the software documented herein. No reproduction, publication, or disclosure of this information, in whole or in part, shall be allowed, unless the prior written consent of Ralink Technology, Inc. is obtained.

NOTE: THIS DOCUMENT CONTAINS SENSITIVE INFORMATION AND HAS RESTRICTED DISTRIBUTION.

Product Name	RT2500USB
Interface Supported	USB
Install Package Version	STA_2500USB D-1.1.1.0 UI-1.1.4.0
Driver Version	1.1.1.0
User Interface Version	1.1.4.0
Date	2005-10-20
OS Support	10.4.X

System Requirement:

RT2500USB drivers require OS 10.2.5 or above.

NOTE: For end-users previously installed OEM provided package. Please uninstall it before running this Ralink released package.

Hardware Supported

Ralink RT2500 chipset USB

Release History:

STA 2500USB D-1.1.1.0 UI-1.1.4.0 2005 10 20

Driver:

1. Fix Low Performance
2. Fix Power Saving Mode.

UI

1. Fix RTS Error Handling.
2. Fix WEP ASCII Field Error Handling.

STA 2500USB D-1.1.0.0 UI-1.1.1.0 2005 09 13

Driver:

3. Fix WPA-PSK (TKIP & AES) Disconnecting Problem.